

## Official Release 1.0.9

- RND-20260008 - Discovery does not work in case DHCP Server is not available on the LMP SH-HRNL device  
Component: Discovery | Created: 2026-04-04